



PATENTED PEG BLANK

- 1. TURN TO ROUGH DIMENSION,
- 2. THEN SHAPE TAPER,
- 3. THEN FIT TO INSTRUMENT
- 4. MARK PEGHEAD FACE
- 5. PUT BACK INTO LATHE AND FINISH



Drawn by Chuck Chandler, © 2014 All rights reserved Dimensions in mm Print full scale 8-1/2"x11"